

H.C.B-G1560 FUSO (330) TRUCK DIFFERENTIAL MAIN SHAFT BEARING EXTRACTOR



* Normally, the removal of bearing is done by cutting, but it'll cause the damage of main shaft.

Rating: Not Rated Yet
Price:

Sales price:
Discount:

[Ask a question about this product](#)
Manufacturer: [HCB Specialty Tools](#)

Description

Copyright © 2019 HCB Specialty Tools. All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or by any information storage and retrieval system, without permission in writing from HCB Specialty Tools.

Warning: The removal of bearing is done by cutting, but it'll cause the damage of main shaft.

Always use the correct size of bearing and follow the correct procedure to avoid any damage to the main shaft.

HCB Specialty Tools is not responsible for any damage caused by the use of this tool.

